

MEZ 44/1/65

# TECHNICAL SERVICE BULLETIN

NO. 75-B-6A



# Triumph

August, 1975

SUBJECT:  
  
AIR CONDITIONING FUSE FAILURE

MODELS:  
  
TR7

Please refer to Bulletin 75-B-6, and note the following part numbers have been changed as follows:

- Two Lucas 17 Amp Fuse - Part #188218
- One 6RA Relay - Part #33293
- One Line Fuse Holder - Part #54190387

Provided Courtesy Triumph Wedge Owners Association  
<http://www.triumphwedgeowners.org>

A.H.