

# TECHNICAL SERVICE BULLETIN

NO. 75-D-3

BRITISH



LEYLAND

# Triumph

March, 1975

SUBJECT:

GEARBOX OIL LEAKS

MODELS:

ALL MODELS

When investigating gearbox oil leaks, it should be remembered that a blocked breather hole can cause pressure build-up within the gearbox unit, and consequently oil seals may be changed erroneously.

The gearbox breather is located on the top cover of the transmission, and should be checked for any blockage prior to undertaking any major disassembly.

J.P.