

NO. 79/Z/4-B



# Recall Campaign Bulletin

**SUBJECT:**AMENDMENT TO RECALL A457  
HEADLAMP MOTOR**MODELS:**

1975 - 78 TR7

May 1980

It has been noted that on occasion, when performing the recall, the main hinge has been found with the center cross web broken out. As this breakage is generally a result of outside influences and not as a result of the malfunction of the recall related components, there will be no reimbursement for hinge assembly replacements.

A second, more isolated problem has been noted which concerns the seizure of the hinge. Should this condition be encountered and cannot be corrected with lubricant, replacement will be covered upon completion of a P.R. authorization.