

ITEM T80/027

SUBJECT: COOLING SYSTEM PLUGS

MODELS: All

Please note that the plastic or aluminum plugs fitted to some models are no longer serviced by Parts Department.

Brass plug, part number JRT 601048, is the recommended replacement.

Refer to Technical Service Bulletin, September/October 1980; T80/022 and Parts Information Bulletin October 1980; 80-1B-10 for additional information.

H.C.T.