

# TECHNICAL SERVICE BULLETIN

NO. 75-B-1



# Triumph

May, 1975

SUBJECT:

ELECTRONIC TYPE IGNITION SYSTEM

MODELS:

SPITFIRE 1500, TR7

The 1975 Spitfire 1500 and TR7 models are now equipped with a Lucas electronic ignition system. Please note the amplifier unit which is attached to the distributor body will not be serviced separately. Therefore, should this component require replacement during the warranty period, a complete distributor assembly must be installed.

Dealers are requested to return the displaced units (amplifier and distributor assembly) to their distributors in accordance with the current vendor warranty arrangements.

J.P.