

TECHNICAL SERVICE BULLETIN

76-B-10C

NO.



Triumph

January, 1977

SUBJECT:

SERVICING OF ELECTRONIC MODULES FOR
IN-BUILT ELECTRONIC DISTRIBUTORS

MODELS:

Spitfire 1500
TR7

Listed below is the cross-reference information for electronic distributors, amplifiers and vacuum units fitted to 1977 model vehicles.

This information is to be used in conjunction with the information and instructions contained in the original Triumph Technical Service Bulletin #76-B-10, dated October, 1976 and is to replace Triumph Technical Service Bulletin #76-B-10B which should be destroyed.

<u>Vehicle</u>	<u>Dist.</u>	<u>Amplifier Vac. Assy.</u>	<u>Vacuum Unit</u>	<u>Remarks</u>
Triumph Spitfire Fed. 1977	41697	54429790	54429788	
Triumph Spitfire Cal. 1977	41698	54429455	54427198	
Triumph TR7 Fed. 1977	41701	83502		Use 41701 No Vac. Unit
Triumph TR7 Cal. 1977	41700	54429757		

TS/Lucas