

# SERVICE & PARTS TECHNICAL INFORMATION

NO.

79-D-2



# Triumph

October, 1979

SUBJECT:

5-SPEED GEARBOX  
LAYGEAR END FLOAT

MODELS:

TR7

When rebuilding the TR7 5-speed gearbox please note that the laygear end float has been changed from .0002" to .002" end float to .001" end float to .002" pre-load.

Section 37.20.04 of the TR7 Repair Operation Manual will be amended at the next printing.

5 (979) H.C.T.